Superseding: New

Effective Date: November 23, 2016

Page: 1 of 25

Padmount PMH Switchgear Condition Assessment



1. Scope

This work practice details the condition assessment procedures for S&C Electric PMH, live-front padmount switchgear.

The inspection procedures contained herein can be performed while the switchgear is energized. Switchgear maintenance that requires de-energizing and grounding is outside the scope of this work practice.

2. Application

This work practice is for qualified Seattle City Light (SCL) personnel who perform inspections on padmount PMH switchgear. Section 4 defines who is qualified to perform this work.

The assessment form associated with this work practice can be obtained from Standards. See Appendix B for an example.

3. Definitions

Equipment (PS) Number - also known as the "PS" number, it is a number that follows the prefix "PS" assigned to each switch. To help explain how this number is used, a PS number could be considered the equivalent of a person's social security number. No matter where a person lives, their social security number remains the same. PS labels are assigned, printed, and attached to the switchgear at the warehouse prior to receiving the equipment.

Standards Coordinator Muneer Shetab Standards Supervisor John Shipek Unit Director Darnell Cola

Mun 6 Stepl Goldfiel

Damel Coh

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016

Page: 2 of 25

Switch (SW) Number – also known as the System Operations Center (SOC) Switch Number, this number follows the prefix "SOC" and indicates the switch circuit location. To help explain how this number is used, an SOC number could be considered the equivalent of a street address. No matter who lives there, the address stays the same.

Parent Facility ID No. – this is also known as the Pad (P) Number, Underground (U) Switch Number, or the Vault (V) Number.

Underground (U) Switch Number – this is a switch number specifically for underground equipment. This number follows the prefix "U."

Pad (P) Number – identifies the pad on which the switch is installed. The best practice is to affix the pad number to the pad itself. Labeling the switch enclosures with the pad number should be avoided.

Vault (V) Number – identifies the vault on which the switch is installed.

4. Safety

WARNING: Do not open or operate the switch if it emits a buzzing, hissing, or crackling sound. Such sounds may indicate presence of corona or partial discharge.

Crews shall also familiarize themselves with and follow the safety information contained in the S&C Data Bulletin 662-90 and Instruction Sheet 662-510.

Padmount switchgear shall only be inspected by qualified personnel who are knowledgeable in installation, operation, and maintenance of underground electrical power distribution equipment along with the associated hazards.

This work practice is intended only for such qualified personnel. The instructions in this work practice are not intended to be a substitute for adequate training and experience in safety procedures for this type of equipment.

A qualified person is one who is trained and competent in:

- Distinguishing exposed live parts from non-live parts of electrical equipment.
- Determining the proper approach distances corresponding to the voltages to which the qualified person will be exposed.
- Properly using the special precautionary techniques, personal protective equipment (PPE), insulating and shielding materials, and insulated tools for working on or near exposed energized parts of electrical equipment.

No body parts shall enter the plane of the switchgear during the inspection while it is energized.

Always use an S&C Grappler attached to a suitable universal pole to insert, remove, or replace front barriers. See Figure 4. No other tools are recommended. Failure to use the proper tools can result in damage to the equipment, flashover, and injury. An S&C Grappler should be located next to the storage rack on the interior fuse compartment door of each unit.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016

Page: 3 of 25

Figure 4. S&C Grappler



Removed front barrier boards shall be placed on a clean surface. Always wipe clean the barriers before placing them back to their suspended position. Do not place the removed barrier boards on the ground because they could become contaminated and present a potential arc flash hazard.

5. Required PPE

The following PPE is required to complete padmount switchgear condition assessment procedures:

- Flame-resistant (FR) clothing that is the appropriate class
- Safety glasses
- Gloves (appropriate type)
- Hard hat
- Safety cones and yellow tape

6. Required Tools and Reference Materials

6.1 Tools

The following tools are required to complete PMH switchgear condition assessment procedures:

- Universal pole insert
- S&C Grappler (included inside each type of PMH switch)
- Flashlight
- Infrared heat sensor gun
- Digital camera
- Tripod
- Switch key/socket

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016

Page: 4 of 25

6.2 Reference Materials

It is recommended that the following reference materials be on hand when conducting the condition assessment procedures:

- SCL 1167.13; "Padmount Switch Signs and Labels"
- S& C Instruction Sheet 662-510
- S&C Data Bulletin 662-90

7. Procedure

Follow all safety and clearance procedures before performing any work on the switch. Proper PPE is required to perform this work practice. See Section 5, "Required PPE."

Part 1: Site and Location

Assessment	Performance Expectations	image Reference
Access to site	 Switch is reasonably accessible to SCL operations and maintenance personnel. Accessing the site does not require a special key, permit, or prior approval for entry, as may be required for locations inside a customer building or facility. 	1a
Compartment access	 Compartments are accessible with adequate space to perform routine operations and maintenance: 10 ft in front of doors, 3 ft on sides. 	1b, 1c

Part 2: Enclosure Exterior and Pad

Assessment	Performance Expectations	Image Reference
Signs and labels	 Warning, danger, and notice signs are easy to read. Switch (SOC) Nur and Equipment (PS) numbers are assigned and easy to read. See SC Work Practice 1167.13 for padmount switch signs and labels. 	
Paint condition	No graffiti, only minor rust, no moss	2b
Pad	 No major cracks, reasonably level 	_
Seal	Enclosure sealed at pad to prevent animal ingress	_
Doors, locks, and latches	 Easy to operate, proper alignment, all latch points engage, locks and F head holts are secure 	Penta –

Part 3: Switch Interior

Assessment	Performance Expectations	lmage Reference
Water ingress	No standing water	3a
Conduits	Sealed	3a
Vapor barrier	Installed	3a
Condensation	 Little or no condensation on roof or walls 	3b
Contamination	Little or no contamination on room or walls.No signs of animal intrusion	-

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 5 of 25

Part 4: Ground Connections

Assessment	Performance Expectations	lmage Reference
Fence	 All fences within six feet of switch are grounded. See SCL U10-1.2, Section A-A. 	4a
Enclosure	 Enclosure is grounded as can be practically determined by visible inspection. See SCL U10-5, Figures 1 and 3. 	4b, 4c
Surge arresters and terminations	 Surge arresters and terminations are grounded. See U10-5, Figure 7. 	4d
Electrical clearances	 The clearance of any energized part to the electrical ground meets the 7-1/2-in minimum air clearance requirements as described in Table 3 of S&C Data Bulletin 662-590. 	4e

Part 5: Barrier Boards

Assessment	Performance Expectations	Image Reference
Installation	 Boards are in place and secured by appropriate 1/4 turn or thumb-screw hardware. Barrier boards are inserted in appropriate barrier guides. 	5a
Physical condition	 No warping or delamination Only minor dirt and contamination. Boards are not wicking, coming apart, discolored, or otherwise damaged. 	5b
Dielectric condition	 Less than 1 square inch of corona caused surface deterioration 	5c
Electrical clearances	 The clearance of any energized part to the barrier board meets the 2-1/4-in minimum air clearance requirements as described in Table 3 of S&C Data Bulletin 662-590. 	4e

Part 6: Terminations

Assessment	Performance Expectations	Image Reference
Terminations	 Only minor contamination, no signs of corona damage, no signs of tracking on surface 	
Installation	 Terminations of the same compartment are of the same style/type. Terminations are straight and do not touch concrete knockouts. Cables are not pulling on terminations. Termination top skirt is below or at the same level as the ground studs. 	6b, 6c
Electrical clearances	 There is at least 6-1/2-in of clearance from the grounding studs to the concentric neutral cable at the base. The clearance of the terminator skirts to the barrier board meets the 1-1/4-in minimum air clearance requirements as described in Table 3 of S&C Data Bulletin 662-590. 	6d, 6e

Part 7: Fuses

Assessment	Performance Expectations	Image Reference
Fuse holders	No signs of overheating	7a
	No signs of tracking	
Fuses	 Little to no surface contamination 	-
	No signs of physical damage	
	No signs of tracking	

Seattle City Light
WORK PRACTICE

Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016

Page: 6 of 25

Part 8: Surge Arresters

Assessment	Performance Expectations	Image Reference
Surge arresters	Little to no surface contamination	8a
	No signs of physical damage	
Electrical clearances	Clearance from the surge arrester connecting rod to the barrier board, to termination skirts, or to the insulating surfaces between the concentric neutral's end and the conductor lug should be at least 2-1/4 inches for 25 kV as described in Table 3 of S&C Data Bulletin 662-590.	4e

Part 9: Insulators

Assessment	Performance Expectations	Reference
Insulator condition	 Little or no surface contamination 	9a
	 No signs of physical damage 	

Part 10: Switch

Assessment	Performance Expectations	Image Reference
Switch contacts	No signs of overheatingOnly minor erosion	10a
Electrical clearances	 Clearance from the grounding studs to the barrier board should be at least 2-1/4 inches for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. 	4e

Notes:

In 2005 S&C Electric Company changed the design of Mini-Rupter switches used in their type of padmount PMH switchgear lineup:

- Pre-2005 Design: In this design version, the strut assembly runs the full length of the switch compartment and it is attached to the switch frame on both ends. With the exception of arc compressors, if something goes wrong with the switch, S&C will provide a new switch that would fit inside the existing switch compartment. (See Image Reference 10b)
- Post-2005 Design: In this design version, the strut assembly does not run the full length of the switch. Instead, it is attached to the switch frame on one side and supported by the lower switch insulators on the other side. The switch inter-phase and end barrier boards are also different in the post-2005 design. (See Image Reference 10c)

Part 11: Heat Sensor Readings

Assessment	Performance Expectations	Image Reference
Ambient temperature	Measure ambient temperature	_
Highest bushing/elbow/fuse or switch contact temperature above ambient	 Less than 10 degrees centigrade above ambient 	-
Comparison of values between the phases of the switch	 Less than 5 degrees centigrade difference between the phases 	_

Part 12: Battery (Remote Supervisory PMH-5 Only)

Assessment	Performance Expectations	lmage Reference
Physical condition	 No damage, deformities, cracks, leaks, rust, or white powder 	-
Electrical condition	 Passes battery test/lamp test 	_

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016

Page: 7 of 25

Part 13: Overall Switch Condition Assessment Rating

Assessment	Performance Expectations	Reference
Overall rating of the switch	Based on the above condition assessments and the expertise of the inspection team, what is an overall assessment of the complete switch?	_

Functional Condition Assessment Rating Guide

- 1 Renewal action taken by inspector, now in acceptable condition.
- 2 Unacceptable, not fit for service, immediate corrective action required. If this rating is given, contact SOC and tag appropriately.
- 3 Marginal condition, schedule renewal activity in the next 6 months
- 4 Deteriorated, but acceptable condition
- 5 Good condition

Part 14: Scheduling Future Out-of-Service Condition Directed Renewal Tasks

Include any out-of-service renewal tasks in this section and indicated the anticipated time frame.

Part 15: Comments

Include all comments related to Parts 1-14 in this section. With each comment provided, identify which part each corresponds to.

8. References

S&C Data Bulletin 662-90, "(S&C Manual PMH Pad-Mounted Gear, Outdoor Distribution Inspection Recommendations)"

S&C Instruction Sheet 662-510, "(S&C Manual PMH Pad-Mounted Gear, Outdoor Distribution Operation)"

SCL 1167.13; "Padmount Switch Signs and Labels"

9. Sources

Shetab, Muneer; SCL Standards Engineer, subject matter expert, and originator of 1167.19 (muneer.shetab@seattle.gov)

Shipek, John; SCL Standards Supervisor and subject matter expert for 1167.19 (john.shipek@seattle.gov)

Superseding: New Effective Date: November 23, 2016 Page: 8 of 25

Appendix A: Procedure Images

Part 1: Site and Location



1a. Switch located inside customer's substation as shown.



1b. Brush surrounding the switch adjacent to SW648 is so dense that it is not accessible.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 9 of 25



1c. Switch is not accessible due to excessive vegetation.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 10 of 25

Part 2: Enclosure Exterior and Pad



2a. Switch is missing danger and warning signs. The existing caution signs are outdated and damaged.



2b. Switch surface is covered with excessive moss and graffiti.

Seattle City Light WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016 Page: 11 of 25

Part 3: Switch Interior



3a. Excessive condensation build up on the insulators and interior of the switch.



3b. Conduits are not sealed and a vapor barrier is not installed.


Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New


Effective Date: November 23, 2016

Page: 12 of 25

Part 4: Ground Connections




4a. Fence Grounding, Section A-A from SCL U10-1.2



4b. Grounding PMH-9, Figure 1 from SCL U10-5.

Superseding: New

Effective Date: November 23, 2016 Page: 13 of 25




4c. Grounding, PMH-5, Figure 3 from SCL U10-5.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016 Page: 14 of 25



4d. Arrester Ground Connection Detail


Rating, kv	Minimum Air Clearances (Inches)				
	Energized Parts to Barriers	Terminator Skirts to Barriers	Energized Parts to Elec. Ground	Phase-to- Phase	
14.4 25	1 2¼	½ 1¼	6 7½	6 7½	

4e. Minimum air clearances table from S&C Data Bulletin 662.590.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 15 of 25

Part 5: Barrier Boards




5a. Barrier boards are contaminated and discolored. One of the barrier boards is secured with a wire tie instead of an appropriate thumb screw.



5b. Barrier boards at the center are bent.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 16 of 25



5c. Signs of electrical activity on the barrier board.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 17 of 25

Part 6:Terminations







6a. Terminations show signs of contamination and electrical activity.



6b. Two terminations on the right side appear to be an older vintage. The termination skirts on the left termination extend far below the ground studs. The alignment of the termination skirts and the ground studs should be similar to one shown in photo 7.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016 Page: 18 of 25



6c. Two terminations on the far left are bent and are pulling on the terminal pads. The termination on the right appears to be touching the concrete pad. The terminal pads are in the Standard position.




6d. Termination is too close to the barrier board.

Seattle City Light WORK PRACTICE Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016 Page: 19 of 25

Part 7: Fuses



7. Excessive signs of contamination on the fuse surfaces. The fuse stud on the far left fuse appears to be discolored compared to the remaining two fuses.

Part 8: Surge Arresters




8. Surge arrester shows signs of contamination.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 20 of 25

Part 9: Insulators




9. Upper and lower fuse insulators show signs of excessive contamination.

Seattle City Light WORK PRACTICE Padmount PMH Switchgear Condition Assessment Superseding: New

Effective Date: November 23, 2016 Page: 21 of 25

Part 10: Switch





10a. Signs of arcing and melting at the disconnect blade.



Left-Side Connection






Right-Side Connection

10b. Pre-2005 PMH Switch strut assembly. Note that the strut assembly runs the full length of the switch and is attached to the switch frame on both ends.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016 Page: 22 of 25



10c. Post-2005 PMH Switch strut assembly. Note that the strut assembly does not run the full length of the switch. It is attached to the frame on one side and supported by the insulator on the other side.

Seattle City Light
WORK PRACTICE
Padmount PMH Switchgear Condition Assessment

Superseding: New

Effective Date: November 23, 2016

Page: 23 of 25

Appendix B: Example of a Padmount PMH Switchgear Condition Assessment Form

	Padmount PMI	H Switchgear Condition Assessment
	(For use	with Work Practice 1167.19)
Inspected By:		Date:
		Parent Facility ID No.:
Switch (SOC) No:		Equipment (PS) No.:
		Serial No.:
Model No.:		_
Part 1. Site and Location	n	
Condition Rating (1-5)	Assessment	Performance Expectations
	Access to site	Switch is reasonably accessible to SCL operations and maintenance personnel. Accessing the site does not require a special key, permit or prior approval for entry, as may be required for locations inside a customer building or facility.
	Compartment access	Compartments are accessible with adequate space to perform routine operations and maintenance - 10 feet in front of doors, 3 feet on sides.
Part 2. Enclosure Exterio		
Condition Rating (1-5)	Assessment	Performance Expectations
	Signs and labels	Warning, Danger, and Notice signs are easily read. Switch (SOC) Number and Equipment (PS) Numbers are assigned and easily read. See SCL Work Practice 1167.13 for padmoutn switch signs and labels.
	Paint condition	No graffiti, only minor rust, no moss
	Pad	No major cracks, reasonably level
	Seal	Enclosure sealed at pad to prevent animal ingress
	Doors. Locks, and latches	Easy to operate, proper alignment, all latch points engage, locks and penta head bolts secure
Part 3. Switch Interior		
Condition Rating (1-5)	Assessment	Performance Expectations
	Water ingress	No standing water
	Conduits	Sealed
	Vapor barrier	Installed
	Condensation	Little to no condensation on roof or walls
	Contamination	Little to no dirt or moss on roof or walls. No signs of animal intrusion
Part 4. Ground Connecti		
Condition Rating (1-5)	Assessment	Performance Expectations
	Fence	All fences within six feet of of switch is grounded. See SCL Construction Standard U10-1.2, Section A-A.
	Endosure	Enclosure is grounded as can be practically determined by visible inspection. See SCL U10-5, Figures 1 and 3.
	Surge arresters and terminations	Surge arresters and terminations are grounded. See SCL U10-5, Figure 7.
	Electrical clearances	The dearance of any energized part to the electrical ground meets the 7-1/2" minimum air clearance requirements as described in Table 3 of S&C Data Bulletin 662-590.

Revision 0 November 21, 2016

Functional Condition Assessment Rating Guide

5 – Good condition; **4**- Deteriorated, but acceptable condition; **3** – Marginal condition, schedule renewal activity in the next 6 months; **2**- Unacceptable, not fit for service, corrective action required. If this rating is given, contact SOC and tag appropriately;

1 – Renewal action taken by inspector, now in acceptable condition

Seattle City Light WORK PRACTICE

Padmount PMH Switchgear Condition Assessment

Superseding: New Effective Date: November 23, 2016

Page: 24 of 25

Condition Rating (1-5)	Assessment	Performance Expectations
	Installation	Boards are in place and secured by appropriate 1/4 turn or thumb-screw hardware
		Barrier boards are inserted in appropriate barrier guides.
	Physical condition	No warping or delamination.
	·	Only minor dirt and contamination. Boards are not wicking, coming apart,
		discolored, or otherwise damaged.
	Dielectric condition	Less than 1 square inch of corona caused surface deterioration
	Electrical clearances	The dearance of any energized part to the barrier board meets the 2-1/4" minimum
		air clearance requirements as described in Table 3 of S&C Data Bulletin 662-590.
Name C. Tanana in a still a second		
art 6. Terminations	0 co coom out	Daufaumanaa Fumaatatiana
Condition Rating (1-5)	Assessment	Performance Expectations
	Terminations	Only minor contamination, no signs of corona damage; no signs of tracking on surface
	Installation	Terminations of the same compartment are of the same style/type.
		Terminations are straight and do not touch concrete knockouts
		Cables are not pulling on terminations.
		Termination top skirt is below or at the same level as the ground studs
	Electrical clearances	There is at least 6-1/2 inches clearance from the grounding studs to the concentric
		neutral cable at the base. The clearance of the terminator skirts to the barrier board
		meets the 1-1/4" minimum air clearance requirements as described in Table 3 of
		S&C Data Bulletin 662-590.
art 7. Fuses		
ondition Rating (1-5)	Assessment	Performance Expectations
	Fuse holders	No signs of overheating
		No signs of tracking
	Fuses	Little to no surface contamination
		No signs of physical damage
		No signs of tracking
	heck box on right if no surge arrester is	
ondition Rating (1-5)	Assessment	Performance Expectations
	Surge arresters	Little to no surface contamination
		No signs of physical damage
	Electrical clearances	Clearance from the surge arrester connecting rod to the barrier board, to
		termination skirts, or to the insulating surfaces between the concentric neutral's
		end and the conductor lug should be at least 2-1/4" for 25 kV as described in Table
		3 of S&C Data Bulletin 662-590.
art 9. Insulators		
Condition Rating (1-5)	Assessment	Performance Expectations
	Insulator condition	Little to no surface contamination
		No signs of physical damage
	itch Interior (Check box on right to indic	ate Mini-Rupter switch style) Pre-2005 Post-2005
art 10. SwitchPart 3. Sw		
	Assessment	Performance Expectations
		Performance Expectations No signs of overheating
	Assessment	
	Assessment Switch contacts	No signs of overheating Only minor erosion
	Assessment	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25
condition Rating (1-5)	Assessment Switch contacts Electrical clearances	No signs of overheating Only minor erosion
ondition Rating (1-5)	Assessment Switch contacts Electrical clearances	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590.
Condition Rating (1-5)	Assessment Switch contacts Electrical clearances	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25
art 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590.
Condition Rating (1-5)	Assessment Switch contacts Electrical clearances dings Assessment	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations
Part 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances dings Assessment Ambient temperature	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations Measure ambient temperature
art 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances dings Assessment Ambient temperature Highest bushing/elbow/fuse or switch	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations
Part 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances dings Assessment Ambient temperature	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations Measure ambient temperature
Part 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances dings Assessment Ambient temperature Highest bushing/elbow/fuse or switch	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations Measure ambient temperature
Part 11. Heat Sensor Rea	Assessment Switch contacts Electrical clearances dings Assessment Ambient temperature Highest bushing/elbow/fuse or switch contact temperature above ambient	No signs of overheating Only minor erosion Clearance from the grounding studs to the barrier should be at least 2-1/4 in for 25 kV as described in Table 3 of S&C Data Bulletin 662-590. Performance Expectations Measure ambient temperature Less than 10 degrees centigrade above ambient

November 21, 2016

Functional Condition Assessment Rating Guide

5 – Good condition; **4**- Deteriorated, but acceptable condition; **3** – Marginal condition, schedule renewal activity in the next 6 months; 2- Unacceptable, not fit for service, corrective action required. If this rating is given, contact SOC and tag appropriately;

1 – Renewal action taken by inspector, now in acceptable condition

Seattle City Light WORK PRACTICE

Padmount PMH Switchgear Condition Assessment

Standard Number: 1167.19

Superseding: New Effective Date: November 23, 2016 Page: 25 of 25

				rvisory PM	H-5 C	Only)		
Condition	n Rating (1-5) Assessment					Performance Expectations		
			Physical condition					No damage, deformities, cracks, leaks, rust or white powder
			Elec	trical cond	ition			Passes battery test/lamp test
Part 13.	Overall	witch C	on di <u>ti</u>	on Assessn	nent l	Rating		
	on Rating			essm ent				Performance Expectations
		` ,	Ove	rall rating	of the	switch		Based on the above condition assessments and the expertise of the inspection team
1								what is an overall assessment of the complete switch?
Part 14.	Scheduli	ng Cond	lition [Directed Re	enew	al Tasks		
	Α	nticipat	ed Tin	ne Fram e (Mont	ths)		
	0-3	-3		2	4-48	Bey	ond 48	Renewal Task
								Cleaning interior walls, roof and barrier boards
								Mechanism lubrication
				Ī				Contact and hinge lubrication with NYE Rheolube 368
				Ī				Installation of vapor barrier on floor of switch (if switch is replaced)
				Ī				Other(s)
Part 15.	Comme	its (inici	uae co	mments	or Pal	115 1-14.	with eac	ch comment provided, identify which part each corresponds to)